Grain moisture measurement made easy with the PFEUFFER HE 50





Quality and precision for the most important measure during the grain harvest. Pfeuffer GmbH
P. O. Box 248
D-97305 Kitzingen

■ Phone +49-9321-9369-0 Telefax +49-9321-9369-50 Internet www.pfeuffer.com



PFEUFFER HE 50

reliable in the field and for drying and storage

Measurement procedure

Place a 9 ml sample in the bottom section of the measurement cell. With the help of a ratchet screw the top section of the measurement cell into place. Place the measurement cell on to the unit and select the product using the rotary switch. By pressing the measurement button the selected product appears in the display. The **HE 50** completes the measurement in seconds, automatically corrects the temperature and displays the measurement result. No adjustment is required since the **HE 50** offers very high accuracy.

Four of the fourteen product programs can be selected from over 200 available products for your **HE 50**, e.g. cargo, peanuts, milo corn, green coffee etc. This allows a universal application of the HE 50 for grain, grass, vegetable and flower seeds, etc. Floury products can be measured by means of the special cell for floury products, available as option.



■ Measurement cell

The measurement cell which has been specially developed for agricultural use allows the most diverse products to be measured. The homogenisation of the sample in the new measurement cell








HE 50 - the precise moisture meter for agriculture

creates the best conditions for precise moisture measurements. This means that the **HE 50** offers great reliability for freshly harvested grain and other crops within a wide measurement range.



Temperature Measurement

The **HE 50** is suitable for the temperature measurement as well. In con-nection with a temperature rod (1 m or 1.5 m) you can measure the temperature in stored goods and piles of grain. The temperature in bales of straw and forage can be measured by means of the new temperature rod for straw and forage.

As a result of its highly modern technology, the **HE 50** is easy to service and offers a long service life.



■ Technical data

Power supply: 9 V battery or accumulator

Dimensions: Unit 220 x 120 x 65 mm

Suitcase:390 x 290 x 85 mm

Weight: approx. 3.2 kg

We reserve the right to make technical modifications!

Pfeuffer Turk Analiz Ölçü Kontrol Sistemleri Ltd. Şti.

Beştepe Mah. Nergiz Sok. No: 7/2 Via Flat İş Mrk. Kat:3 No:87 Yenimahalle - Ankara

Tel: +90 312 248 1351 Fax: +90 312 219 0562

M: +90 532 409 3958

e-mail: serdar@pfeuffer.com.tr



Phone +49 - 93 21 - 93 69 -0 Telefax +49 - 93 21 - 93 69 -50 e-mail info@pfeuffer.com