

A black and white photograph of a marble surface with a prominent diagonal crack running from the top left towards the bottom center. The marble has a veined pattern. The text 'A DERELI T' is overlaid in a thin, white, sans-serif font, centered horizontally and partially obscured by the crack.

A DERELI T

MARBLE ANALYSIS REPORT



CALACATTA BIANCO DOLOMITE

PHYSICAL ANALYSIS

ANALYSIS NAME	NR	RESULT
Water Absorption (%)	TSE EN 13755	0,19
Intensity(gr/cm3)	TSE EN 1936	2,84
Apparent Porosity (%)	TSE EN 1936	0,13
Compressive Strength (Mpa)	TSE EN 1926	69,8-89,6
Knopp Hardness (Mohs)	TSE EN 14205	4-4,5

CHEMICAL ANALYSIS

CaO	—	41,99
MgO	—	25,54
Al2O3	—	< 0,0064
Fe2O3	—	0,02993
SiO2	—	0,0972
P2O5	—	< 0,0015
K2O	—	0,01473
Na2O	—	< 0,03
TiO2	—	< 0,00922
LoI	—	32,27